

DATEN STIRNRADGETRIEBE - MOTOREN ROBASE (6-POLIG, 1~230 V, 50 HZ)
datas spur geared motors ROBASE (6 poles, 1~230 V, 50 Hz)

Übersetzung ratio	zulässiges Drehmoment (Spitze) permitted torque (peak)			Drehzahl speed	Drehmoment der Motortypen torque of motor types			
	Type G Nm	Type V Nm	Type W Nm		36 Nm	46 Nm	66 Nm	86 Nm
i				1/min				
2-stufig $\eta = 81\%$ 2 stages $\eta = 81\%$								
5	6 (10)	-	-	200	0,30	0,45	0,61	0,85
10	6 (10)	-	8 (13)	100	0,61	0,89	1,22	1,70
13,3	6 (10)	-	-	75	0,81	1,19	1,62	2,26
16,6	6 (10)	-	-	60	1,01	1,48	2,02	2,82
20	6 (10)	-	-	50	1,22	1,78	2,43	3,40
3-stufig $\eta = 73\%$ 3 stages $\eta = 73\%$								
25	6 (10)	-	-	40	1,37	2,01	2,74	3,83
33,3	6 (10)	8 (13)	-	30	1,82	2,67	3,65	5,10
50	6 (10)	-	8 (13)	20	2,74	4,02	5,48	7,67
60	6 (10)	-	8 (13)	16,6	3,29	4,82	6,57	9,20
66,6	6 (10)	-	-	15,0	3,65	5,35	7,29	10,21
4-stufig $\eta = 66\%$ 4 stages $\eta = 66\%$								
75	6 (10)	-	8 (13)	13,3	3,71	5,45	7,43	10,40
100	6 (10)	-	8 (13)	10	4,95	7,26	9,90	13,86
125	6 (10)	8 (13)	8 (13)	8	6,19	9,08	12,38	-
150	6 (10)	-	-	6,6	7,43	10,89	14,85	-
200	6 (10)	-	8 (13)	5	9,90	14,52	-	-
250	6 (10)	8 (13)	8 (13)	4	12,38	-	-	-
5-stufig $\eta = 59\%$ 5 stages $\eta = 59\%$								
500	6 (10)	8 (13)	-	2	22,13	-	-	-
1000	6 (10)	8 (13)	-	1	44,25	-	-	-
1333,3	6 (10)	-	-	0,75	59,00	-	-	-

Bei Überschreiten des zulässigen Drehmoments kann das Getriebe beschädigt werden. Three-phase variants offer 10 to 30% more torque.
 Exceeding the maximum permissible torque may lead to gear damage. Three-phase variants offer 10 to 30 % more torque.

© 2021 Rotek GmbH & Co. KG

Nachdruck nur mit schriftlicher Genehmigung, Änderungen und Irrtum für den gesamten Inhalt vorbehalten.

Reprinting only allowed if written permission has been obtained, We reserve the right to make changes to any part of the above content and disclaim liability for any errors it may contain.